

laser METHOD OF DETERMINING WEAR

FIELD OF THE INVENTION

5

The invention relates to a method for determining wear and more particularly a method of using color as an indicator of the degree of both barrel and screw wear in plastic processing equipment such as extruders and reciprocating injection molding machines.

BACKGROUND OF THE INVENTION

Extruders and injection molding machines use a screw to feed material through the machines. The screw has a flight and a channel. In addition, the screw is located inside a barrel. As the screw rotates inside the barrel, the flight advances the material through the barrel. For plastic material, the screw flight is designed to cause the material to melt as it advances through a heated barrel. In addition, the screw may be used to mix two or more materials as they are moved through the barrel. Furthermore, the machine may use several screws.

The machine is designed and manufactured with a predetermined distance between the screw flight and the barrel. During use, the movement of material through the screw and barrel causes wear which increases the distance between the screw flight and the barrel. If the material is abrasive, the wear occurs more quickly.

Generally an increase in wear creates a reduction of the shear rate on the polymer, resulting in less mixing to occur in the barrel. This results in molten polymer with poor homogeneity. A non-homogeneous product causes the risk of fabricating plastic parts which will fail to meet

performance criteria established on the physical properties. Preventive maintenance procedures to monitor screw and barrel wear presently used by the industry require machines to be shut down, disassembled, and physically measured to determine actual wear. This process is time consuming, and generally requires one-half to one full day of lost productivity and the use of high cost maintenance labor, causing the process to be expensive.

A method is needed which can be more efficient and more economical for the determination of screw wear.

SUMMARY OF THE INVENTION

In general, the present invention provides a facile method for evaluating the extent of wear, and for determining when to repair, plastic processing equipment including a screw and barrel, by first establishing a color standard and then evaluating what color results when color samples (made from two differently colored thermal plastics) are processed in such equipment at spaced intervals over time. Because of the decreasing homogeneity that results as the mixing in such equipment deteriorates over time through wear, the resulting color will correspondingly deteriorate in comparison to the color standard and in relation to color samples obtained using equipment at earlier times. The color of the samples can be subjectively and/or objectively evaluated to provide a basis for determining when the equipment should be repaired.

Pursuant to one illustrative embodiment, a first material of a first color and a second material of a second color are fed into the machine to create a resultant third material with a third color. The

resultant third material is either extruded or is injected into a mold to form a part.

More specifically, in this embodiment, a precolored thermoplastic compound is fed into a machine with a custom formulated concentrate (or master batch) of a different color. When these two products are mixed homogeneously, these products will produce a fabricated plastic part uniformly colored in an entirely different shade than the colors of either component.

The color of the part is then measured with a measuring device, such as, for example, a spectrophotometer. The color will change as the screw and barrel wear. The color value obtained may then be compared with previous color values, obtained at other times during the equipment use, to determine the amount of wear.

Specifically, the method would be performed when the machine is new (or first used or repaired) in order to obtain an initial or first color value. The first value would be placed on a graph with operating time along the X axis and color along the Y axis. After the specified interval of operating time, the method would be performed again to obtain a second color value and this second value would be placed on the graph. Similarly, the method would be performed after each specified interval of operating time to obtain the third value, fourth value, etc. The values would then be connected with a line to form a curve. The user would analyze the curve to determine when the color and wear has diminished below an acceptable level. The machine would then be disassembled and rebuilt.

In this fashion, a straightforward method for evaluating plastic processing equipment wear is provided which avoids the expense and down time of prior techniques. This method can be carried out in a number of different ways, providing as rigorous and objective analysis as the user considers appropriate for the particular equipment repair sequence. Moreover, this method can take advantage of color compounders who have the ability to insure that the proper color samples are used each time for this comparative method, as well as to provide the color change analysis and determination, as the equipment user deems appropriate.

BRIEF DESCRIPTION OF THE DRAWINGS

Fig. 1 is a partial schematic cross-sectional view of an extruder or an injection molding machine.

Fig. 2 is a graph showing the wear of the machine by plotting color (C^* (chroma)) versus specified intervals of operating time.

Fig. 3 is a graph showing the wear of the machine by plotting color (b^*) versus specified intervals of operating time.

Fig. 4 is a perspective view of a part showing some of the locations where color may be measured to obtain differences in color.

Fig. 5 is a graph showing the wear of the machine by plotting color (C^* (chroma)) versus specified intervals of operating time for processing different types of material.

DESCRIPTION OF THE EMBODIMENTS

The invention involves a method which uses color to determine the wear of the screw and barrel. The method can be performed quickly and does not require disassembling the machine or the measurement of its components. The method measures the color and/or color variation to determine the wear.

10 In a precolored thermoplastic compound, the colorant has been homogeneously distributed throughout the polymer during the melt compounding process known as precolor compounding. This compound can be changed to a new color by adding a new colorant. For example, a precolor yellow
15 compound may be changed to a green compound simply through the addition of a blue colorant to the formulation. Therefore, a standard for optimum homogeneity can be established by preparing a precolored green compound, based on both the yellow and blue
20 colorants via the melt-compounding process.

This invention utilizes the principle that normal and continuous use of plastic processing equipment erodes the mixing capability inherent at time of equipment
25 purchase. Thus, as the wear continues, the capability of the equipment to deliver melt homogeneity is also compromised.

A homogenous precolor plastic compound is mixed with
30 a concentrate (or master batch) of a second color. A resultant third material with a resultant third color is created and the color of this third color will depend on its resulting homogeneity.

The color concentrate includes a colorant. The colorant may be a pigment, a dye, a combination of pigment and dye, or other colored material.

5 A precolored yellow thermoplastic compound provides a "background color" that is homogeneous. The addition of an "accent color" such as blue in the form of a concentrate (or master batch) requires complete mixing to attain the homogeneity of the resultant third material
10 which is green. Less than complete mixing will leave "islands" or "swirls" of the concentrate in the resultant third material. In other words, the result is a non-homogeneous background color. If all of the colorant contained in the concentrate was uniformly mixed into the
15 homogeneous precolor compound (background color), the resultant third color will equal the color of the standard developed as the homogeneous standard.

20 If the mixing is compromised and the concentrate (the accent color) is not spread homogeneously throughout the homogeneous precolored compound, the third color will be less than the color of the homogeneous standard. The further the mixing action is compromised, the greater the loss of the third color. The amount of colorant or the
25 like in the concentrate remains identical for each test. Thus, the loss of mixing capability in the processing equipment produces molten polymer containing "islands" or "swirls" of incompletely mixed colorant. This non-homogeneity of the third color manifests itself through a
30 change in color.

Fig. 1 shows certain portions of an extruder or a reciprocating injection screw machine 50. The machine 50 includes a first hopper or feeder 52, a second hopper or
35 feeder 54, a barrel 56 and a screw 58. The screw 58 has a flight 60 and a channel 62. The screw 58 is located

inside the barrel 56 and the screw flight 60 is separated from the barrel 56 by a distance 70. The machine is designed and manufactured with a predetermined distance 70 between the screw flight 60 and the barrel 56. The screw 58 rotates inside the barrel 56 and the screw flight 60 advances the material through the barrel 56. The material is then fed through a die 76 or injected into a mold for injection molding.

10 The method for determining wear is performed as follows. A first material 100 of a first color and a second material 102 of a second color are fed into the machine to create a third material 104 with a third color. For example, the first material 100 may be plastic pellets which are yellow. The second material 102 may be a color concentrate which is blue. The color concentrate may be in a pellet form or may be in a liquid form. The yellow material mixes with the blue material to create a resultant third material 104 which is green.

20 Specifically, the first material is a precolored thermoplastic polymer which is fed into a machine with a second material which is a custom formulated concentrate (master batch) of a different color. The concentrate may be in the solid pelletized state or in the liquid form. The color concentrate includes a colorant. The colorant may be a pigment, a dye, a combination of pigment and dye, or other colored material. The precolored yellow material is mixed/blended with a blue concentrate to form fabricated plastic parts which are green.

The first material 100 is fed into the machine using the first hopper 52 and the second material 102 is fed into the machine using a volumetric feeder or a gravimetric feeder 54. In another embodiment, the first material and second material may be premixed prior to

loading in the first hopper 52. For example, the first material may be yellow plastic pellets which are premixed with blue plastic pellets to create a mixture of yellow pellets and blue pellets.

5

The first and second materials 100, 102 are advanced through the screw 58 and barrel 56 of the machine. As the materials are advanced, the materials melt and are mixed together to form a resultant third material 104 with a third color. The resultant third material 104 is either extruded to form a part or is injected into a mold to form a part.

The color of the part is then measured subjectively, or, more preferably objectively, with any suitable device. Illustrative examples of useful measuring devices include spectrophotometers, 3 or 4 filter tristimulus colorimeters, spectrocolorimeters, electronic video systems, or still frame camera-based systems.

20

The color may be measured by any system desired, preferably using $L^*a^*b^*$ values which are known by persons skilled in the art. It is known that color applied to a surface can be defined in terms of a color in a three-dimensional color space or color map. The ideal color space is a cylinder. The color sphere is defined by the lightness ("L") value, the red/green ("a") value, and the blue/yellow ("b") value. See, for example, Color Measurements Instrument Manual, X-Rite® No. 948-968 (1990) and Commission International de l'Eclairage as the CIE 1976 $L^*a^*b^*$ Color Space. Thus, the three values when combined define a color of an object as seen by the human eye. Any given color can then be measured in terms of the " $L^*a^*b^*$ " value and expressed in relation to the $L^*a^*b^*$ value of a prior measurement. In addition, color may be expressed by C^* (chroma) or by h (hue angle). The

35

value C^* equals $\sqrt{a^{*2} + b^{*2}}$. The value h equals the arctangent of b^*/a^* . Furthermore, color change can be expressed by ΔE which equals

$$\sqrt{(L^*_1 - L^*_2)^2 + (a^*_1 - a^*_2)^2 + (b^*_1 - b^*_2)^2}.$$

5

The color of the fabricated plastic parts will change as the screw 58 and barrel 56 wear. Specifically, color changes because less mixing occurs as the distance 70 between the screw 58 and the barrel 56 increases causing the colorants of the second material to become less homogeneously distributed in the third resultant material.

The color value would then be compared with previous color values to determine the amount of wear. Specifically, the method would be performed on the machine 50 when the machine is new (or first used or repaired) in order to obtain a first or initial color value 120. In this example, the color value is C^* (chroma). Referring to Fig. 2, the first value 120 would be placed on a graph 122 with operating time 124 along the X axis and color 126 along the Y axis. After the specified interval of operating time 128, the method would be performed again to obtain a second color value 130 and this second value 130 would be placed on the graph 122. Similarly, the method would be performed after each additional interval of operating time 132, 134 to obtain the third value 136, fourth value 138, etc. The values would then be connected with a line to form a curve 142. In this example, the first material is a precolored compound and the second material is a color concentrate. The first color is yellow, the second color is blue and the resultant third color is green. The curve moves upward because the yellow becomes more dominant in the third color and makes the resultant third

(green) color brighter and more yellow. The user would analyze the curve 142 to determine the time when the color, and thus wear, would reach a predetermined unacceptable value 144. The machine would then be
5 disassembled and rebuilt at the specified time.

In other examples, and depending upon the colors used, the color value a^* , b^* , L^* , h , or ΔE may be used as the color value to be placed upon the graph. For
10 example, referring to Fig. 3, the graph 150 shows an example where the color value is b^* and the curve 152 moves downward. In this example, the first material is a precolored compound and the second material is a color concentrate. The first color is white, the second color
15 is blue and the resultant third color is light blue. The curve 152 moves upward because the white becomes more dominant in the resultant third color and makes the resultant third color duller and more white.

20 In another embodiment, the color values would be compared to the color value of a color chip. In an additional embodiment, the color values would be compared to the color value of a control part with a specified control color.

25

In another embodiment, a mathematical equation would be created which represents the relationship between the color values and the time period. The equation would be used to determine the time when the color will reach a
30 predetermined value. The machine would then be disassembled and rebuilt at the specified time. The equation could be created using a computer and appropriate software.

35 In another embodiment, the color is measured at several locations on the part and the values are compared

with a standard for differences. If the differences in color values at the locations are unacceptable, then these differences would indicate wear in the machine. As the machine wears, the mixing decreases and the
 5 difference between color values at various locations increases. For example, referring to Fig. 4, the color is measured at five locations, 160, 162, 164, 166, 168 on a specified area on the part 170. The color values are compared with a standard and if unacceptable differences
 10 in color values exist, then the machine would be disassembled and rebuilt.

In another embodiment, a graph or equation is created for a particular model number of a machine by a
 15 specific manufacturer. For example, as shown in Fig. 5, a graph 200 is created for a machine by manufacturer X with model number Y. The graph may have several lines for different wear rates depending on the abrasiveness of the first and second materials. For example, the graph
 20 200 may have a first line 202 for low abrasive materials, a second line 204 for medium abrasive materials, and a third line 206 for high abrasive materials. The manufacturer or a service company would create the graph for a specific model number using the method noted above.
 25 After a specific period of operating time, the method would be performed to obtain the color value 210 of the third color. After obtaining the color value 210, the appropriate line is selected, e.g. medium abrasive materials 204, and the color value 210 and time 212 are
 30 located on the line 204. By knowing the location on the line, the time 214 when the machine would reach the predetermined value 216 of unacceptable color can be determined. This method could also be performed using equations as noted above.

In a further embodiment, the first material with a first color and the second material with a second color are processed in the machine to obtain a resultant third material with a third color. The machine is then purged or cleaned. A fourth material is then processed in the machine. The fourth material contains the same colorant at the same percentage as the resultant third material, except the fourth material is completely homogeneous prior to processing in the machine. Thus, the fourth material with the fourth color will become the homogeneous color standard. More specifically, the fourth color represents a homogeneous color standard for the particular thermal history and operating conditions of the machine. If the machine has been in use for a period of time, then this color standard (resultant fourth color) would represent the machine when it was new and was providing a completely homogeneous output. The resultant third color is then compared with the color standard (resultant fourth color) to determine the difference between the color values and thus, the wear.

In another embodiment, the method may be performed on a new machine or on a rebuilt machine in order to certify that the machine is performing at an acceptable level. Specifically, the first material with a first color and the second material with a second color are processed in the machine to obtain a resultant third material with a third color. The third color is measured and compared to a color chip, a control part with a control color, and/or with a fourth color as noted herein. In addition, the fourth material with the fourth color may be processed in the machine to obtain a resultant fourth color for the particular thermal history and operating conditions of the machine. The resultant fourth color is then compared with other color values as noted herein. If the machine is new, then the resultant

third color and/or resultant fourth color may be compared with color values of other new machines. If the machine has been rebuilt, then the resultant third color and/or resultant fourth color may be compared with color values
 5 obtained prior to rebuilding the machine.

Preferably, the first material should have an opaque first color. However, in another embodiment, the first material may be a natural resin with a natural first
 10 color and the second material may be a color concentrate with a second color. The natural resin with the natural first color is relatively transparent and provides a poorer base for the second color as opposed to an opaque base. However, the color value of the resulting third
 15 color can be measured and the color can be compared with previous color values to determine the amount of wear. In this embodiment, the user can continue to run saleable parts with the usual color, as opposed to parts with a special color for the wear test which would not be
 20 saleable due to the special color. Indeed, by adopting a test protocol based upon the color and part most normally made on the machine being tested, the timing of the testing can be more easily scheduled, causing little, if any, disruption to the desired production schedules.
 25 In yet another embodiment, the first material may be a natural resin with a natural first color and the second material may be a colorant with a second color. The colorant may be a pigment, a dye, a combination of pigment and dye, or other colored material. The pigment
 30 may be dry or a paste.

Any combination of colored materials, whose colorimetric values (all or any) would be sensitive to change, may be used. For example, other color
 35 combinations may be used as shown in the table below.

	<u>First Color of First Material</u>	<u>Second Color of Second Material</u>	<u>Third Color of of Resultant Third Material</u>
5	Red	Yellow	Orange
	Red	Green	Grey
	Green	Blue	Blue Green
	Blue	Red	Violet
	White	Black	Grey
10	White	Blue	Light Blue

Certain combinations have greater sensitivity to non-homogeneity.

- 15 In order to obtain accurate results for the color values, as is desired in the most preferred embodiment of this invention, so as to achieve the maximum benefits, all variables should be eliminated or controlled. For example, the first and second materials should be the same at each interval measurement. Specifically, the
- 20 first material should be the same product from the same manufacturer for each interval measurement. Similarly, the second material should be the same product from the same manufacturer for each interval measurement. The
- 25 first material and the second material should be of a uniform and consistent pellet size (or particle size) and configuration. In addition, the color (hue), the strength (chroma), and the shade of the first and second materials require tight color tolerance control. If a
- 30 different product and/or manufacturer is used, variables are introduced into the method, such as, the size and composition of the pellets. Furthermore, the same mold should be used for each interval measurement. If a different mold is used, variables are introduced into the
- 35 method, such as, differences in surface texture. In addition, the operation of the machine should be controlled, for each interval measurement, such as, the

back pressure, the screw speed, holding time, dwell time, cylinder temperature, size of nozzle and nozzle shape.

5 The method may be performed by a service company as a service for the user of the machine. The service company would perform the interval measurements and provide the data and recommendations to the user. Inasmuch as precolor services are available and being used to provide color concentrates for normal production, 10 such services have the expertise to provide appropriate test protocols and color samples.

15 In some situations, the method may be completely performed by the user if the user has the skills and equipment. In other situations, some steps in the method may be performed by the user, while other steps may be performed by the service company. For example, the service company can provide the user with the first and second materials separately or in a premixed form. The 20 user then performs the method at the specified time interval and sends the fabricated part to the service company for analysis, including measurement of the color intensity value. The service company then graphs, or otherwise evaluates, the values and provides the data and 25 recommendations to the user.

30 In another embodiment, the user supplies the first and second materials and performs the method at the specified time interval. The user then sends the part to the service company for analysis, including measurement of the color intensity value. The service company then graphs, or otherwise evaluates, the values and provide the data and recommendations to the user.

35 In yet another embodiment, the method may be performed on a new machine by the manufacturer or on a

rebuilt machine by the rebuilder in order to certify that the machine is performing at an acceptable level.

While certain features of the invention have been
5 illustrated and described herein, modifications,
substitutions, changes, and equivalents may occur to
those skilled in the art. It is, therefore, to be
understood that the appended claims are intended to cover
all such modifications and changes as fall within the
10 true spirit of the invention.

11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844
845
846
847
848
849
850
851
852
853
854
855
856
857
858
859
860
861
862
863
864
865
866
867
868
869
870
871
872
873
874
875
876
877
878
879
880
881
882
883
884
885
886
887
888
889
890
891
892
893
894
895
896
897
898
899
900
901
902
903
904
905
906
907
908
909
910
911
912
913
914
915
916
917
918
919
920
921
922
923
924
925
926
927
928
929
930
931
932
933
934
935
936
937
938
939
940
941
942
943
944
945
946
947
948
949
950
951
952
953
954
955
956
957
958
959
960
961
962
963
964
965
966
967
968
969
970
971
972
973
974
975
976
977
978
979
980
981
982
983
984
985
986
987
988
989
990
991
992
993
994
995
996
997
998
999
1000
1001
1002
1003
1004
1005
1006
1007
1008
1009
1010
1011
1012
1013
1014
1015
1016
1017
1018
1019
1020
1021
1022
1023
1024
1025
1026
1027
1028
1029
1030
1031
1032
1033
1034
1035
1036
1037
1038
1039
1040
1041
1042
1043
1044
1045
1046
1047
1048
1049
1050
1051
1052
1053
1054
1055
1056
1057
1058
1059
1060
1061
1062
1063
1064
1065
1066
1067
1068
1069
1070
1071
1072
1073
1074
1075
1076
1077
1078
1079
1080
1081
1082
1083
1084
1085
1086
1087
1088
1089
1090
1091
1092
1093
1094
1095
1096
1097
1098
1099
1100
1101
1102
1103
1104
1105
1106
1107
1108
1109
1110
1111
1112
1113
1114
1115
1116
1117
1118
1119
1120
1121
1122
1123
1124
1125
1126
1127
1128
1129
1130
1131
1132
1133
1134
1135
1136
1137
1138
1139
1140
1141
1142
1143
1144
1145
1146
1147
1148
1149
1150
1151
1152
1153
1154
1155
1156
1157
1158
1159
1160
1161
1162
1163
1164
1165
1166
1167
1168
1169
1170
1171
1172
1173
1174
1175
1176
1177
1178
1179
1180
1181
1182
1183
1184
1185
1186
1187
1188
1189
1190
1191
1192
1193
1194
1195
1196
1197
1198
1199
1200
1201
1202
1203
1204
1205
1206
1207
1208
1209
1210
1211
1212
1213
1214
1215
1216
1217
1218
1219
1220
1221
1222
1223
1224
1225
1226
1227
1228
1229
1230
1231
1232
1233
1234
1235
1236
1237
1238
1239
1240
1241
1242
1243
1244
1245
1246
1247
1248
1249
1250
1251
1252
1253
1254
1255
1256
1257
1258
1259
1260
1261
1262
1263
1264
1265
1266
1267
1268
1269
1270
1271
1272
1273
1274
1275
1276
1277
1278
1279
1280
1281
1282
1283
1284
1285
1286
1287
1288
1289
1290
1291
1292
1293
1294
1295
1296
1297
1298
1299
1300
1301
1302
1303
1304
1305
1306
1307
1308
1309
1310
1311
1312
1313
1314
1315
1316
1317
1318
1319
1320
1321
1322
1323
1324
1325
1326
1327
1328
1329
1330
1331
1332
1333
1334
1335
1336
1337
1338
1339
1340
1341
1342
1343
1344
1345
1346
1347
1348
1349
1350
1351
1352
1353
1354
1355
1356
1357
1358
1359
1360
1361
1362
1363
1364
1365
1366
1367
1368
1369
1370
1371
1372
1373
1374
1375
1376
1377
1378
1379
1380
1381
1382
1383
1384
1385
1386
1387
1388
1389
1390
1391
1392
1393
1394
1395
1396
1397
1398
1399
1400
1401
1402
1403
1404
1405
1406
1407
1408
1409
1410
1411
1412
1413
1414
1415
1416
1417
1418
1419
1420
1421
1422
1423
1424
1425
1426
1427
1428
1429
1430
1431
1432
1433
1434
1435
1436
1437
1438
1439
1440
1441
1442
1443
1444
1445
1446
1447
1448
1449
1450
1451
1452
1453
1454
1455
1456
1457
1458
1459
1460
1461
1462
1463
1464
1465
1466
1467
1468
1469
1470
1471
1472
1473
1474
1475
1476
1477
1478
1479
1480
1481
1482
1483
1484
1485
1486
1487
1488
1489
1490
1491
1492
1493
1494
1495
1496
1497
1498
1499
1500
1501
1502
1503
1504
1505
1506
1507
1508
1509
1510
1511
1512
1513
1514
1515
1516
1517
1518
1519
1520
1521
1522
1523
1524
1525
1526
1527
1528
1529
1530
1531
1532
1533
1534
1535
1536
1537
1538
1539
1540
1541
1542
1543
1544
1545
1546
1547
1548
1549
1550
1551
1552
1553
1554
1555
1556
1557
1558
1559
1560
1561
1562
1563
1564
1565
1566
1567
1568
1569
1570
1571
1572
1573
1574
1575
1576
1577
1578
1579
1580
1581
1582
1583
1584
1585
1586
1587
1588
1589
1590
1591
1592
1593
1594
1595
1596
1597
1598
1599
1600
1601
1602
1603
1604
1605
1606
1607
1608
1609
1610
1611
1612
1613
1614
1615
1616
1617
1618
1619
1620
1621
1622
1623
1624
1625
1626
1627
1628
1629
1630
1631
1632
1633
1634
1635
1636
1637
1638
1639
1640
1641
1642
1643
1644
1645
1646
1647
1648
1649
1650
1651
1652
1653
1654
1655
1656
1657
1658
1659
1660
1661
1662
1663
1664
1665
1666
1667
1668
1669
1670
1671
1672
1673
1674
1675
1676
1677
1678
1679
1680
1681
1682
1683
1684
1685
1686
1687
1688
1689
1690
1691
1692
1693
1694
1695
1696
1697
1698
1699
1700
1701
1702
1703
1704
1705
1706
1707
1708
1709
1710
1711
1712
1713
1714
1715
1716
1717
1718
1719
1720
1721
1722
1723
1724
1725
1726
1727
1728
1729
1730
1731
1732
1733
1734
1735
1736
1737
1738
1739
1740
1741
1742
1743
1744
1745
1746
1747
1748
1749
1750
1751
1752
1753
1754
1755
1756
1757
1758
1759
1760
1761
1762
1763
1764
1765
1766
1767
1768
1769
1770
1771
1772
1773
1774
1775
1776
1777
1778
1779
1780
1781
1782
1783
1784
1785
1786
1787
1788
1789
1790
1791
1792
1793
1794
1795
1796
1797
1798
1799
1800
1801
1802
1803
1804
1805
1806
1807
1808
1809
1810
1811
1812
1813
1814
1815
1816
1817
1818
1819
1820
1821
1822
1823
1824
1825
1826
1827
1828
1829
1830
1831
1832
1833
1834
1835
1836
1837
1838
1839
1840
1841
1842
1843
1844
1845
1846
1847
1848
1849
1850
1851
1852
1853
1854
1855
1856
1857
1858
1859
1860
1861
1862
1863
1864
1865
1866
1867
1868
1869
1870
1871
1872
1873
1874
1875
1876
1877
1878
1879
1880
1881
1882
1883
1884
1885
1886
1887
1888
1889
1890
1891
1892
1893
1894
1895
1896
1897
1898
1899
1900
1901
1902
1903
1904
1905
1906
1907
1908
1909
1910
1911
1912
1913
1914
1915
1916
1917
1918
1919
1920
1921
1922
1923
1924
1925
1926
1927
1928
1929
1930
1931
1932
1933
1934
1935
1936
1937
1938
1939
1940
1941
1942
1943
1944
1945
1946
1947
1948
1949
1950
1951
1952
1953
1954
1955
1956
1957
1958
1959
1960
1961
1962
1963
1964
1965
1966
1967
1968
1969
1970
1971
1972
1973
1974
1975
1976
1977
1978
1979
1980
1981
1982
1983
1984
1985
1986
1987
1988
1989
1990
1991
1992
1993
1994
1995
1996
1997
1998
1999
2000
2001
2002
2003
2004
2005
2006
2007
2008
2009
2010
2011
2012
2013
2014
2015
2016
2017
2018
2019
2020
2021
2022
2023
2024
2025
2026
2027
2028
2029
2030
2031
2032
2033
2034
2035
2036
2037
2038
2039
2040
2041
2042
2043
2044
2045
2046
2047
2048
2049
2050
2051
2052
2053
2054
2055
2056
2057
2058
2059
2060
2061
2062
2063
2064
2065
2066
2067
2068
2069
2070
2071
2072
2073
2074
2075
2076
2077
2078
2079
2080
2081
2082
2083
2084
2085
2086
2087
2088
2089
2090
2091
2092
2093
2094
2095
2096
2097
2098
2099
2100
2101
2102
2103
2104
2105
2106
2107
2108
2109
2110
2111
2112
2113
2114
2115
2116
2117
2118
2119
2120
2121
2122
2123
2124
2125
2126
2127
2128
2129
2130
2131
2132
2133
2134
2135
2136
2137
2138
2139
2140
2141
2142
2143
2144
2145
2146
2147
2148
2149
2150
2151
2152
2153
2154
2155
2156
2157
2158
2159
2160
2161
2162
2163
2164
2165
2166
2167
2168
2169
2170
2171
2172
2173
2174
2175
2176
2177
2178
2179
2180
2181
2182
2183
2184
2185
2186
2187
2188
2189
2190
2191
2192
2193
2194
2195
2196
2197
2198
2199
2200
2201
2202
2203
2204
2205
2206
2207
2208
2209
2210
2211
2212
2213
2214
2215
2216
2217